

GPOP - Issue Review System

Part Number: 5LT86XDVA\$, 5NB13DX9A\$, 5NB13LA8A\$, 5NB13LU7A\$, 5NB131A8A\$, 5NB131U7A\$, 5NB131X9A\$, 5NB132U7A\$, 5NB132X9A\$, 5NB134X9A\$, 5NB15DX9A\$, 5NB15LA8A\$, 5NB15LU7A\$, 5NB43DX9A\$, 5NB43LU7A\$, 5RS31DX9A\$, 6BZ37DX9A\$, 6BZ38DX9A\$, 6BZ383X9A\$, 6CG35DX9A\$

Part Description: Center Console

Issue Description: If vehicle comes in for squeaking, clicking, or binding of the center console lid, verify the complaint by cycling the upper console lid. Check for a green dot sticker on the back of the console behind the rear panel by the hinge.

~

If the above complaint is verified and the console DOES NOT have a green dot sticker near the hinge (behind the back panel), order kit PN 68315574AA and install per the included instructions. Otherwise continue with the repair. Please reference TSB 23-001-16 Rev. E (or later version).

~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.